GOVERNMENT OF TELANGANA ABSTRACT

Minor Irrigation – Krishna Basin- Siddipet District – "Mission Kakatiya Phase-III" - "Comprehensive Restoration of (28) Minor Irrigation tanks in Siddipet District – Administrative approval for an amount of Rs.868.73 Lakhs - Accorded – Orders - Issued.

IRRIGATION & CAD (MK) DEPARTMENT

G.O.Rt.No. 304

Dated: 27-03-2017 Read the following:-

- 1. From the Chief Engineer, Minor Irrigation(KB), Hyderabad, Lr. No. DCE-I/OT1 AEE5 / Mission Kakatiya III /Siddipet/List–X/2017, Dt: 22-02-2017.
- 2. From the Chief Engineer, Minor Irrigation, Hyderabad, Lr.No. 20193/ DCE-II/ OT1/TO2/Budget/checkslips/2017, Dt.19-01-2017.
- 3. From the Chief Engineer, Minor Irrigation, Hyderabad, Lr.No.CE/ MI/ DCE1/OT1/AEE5/Finance Department/Remarks/2017, dated:09-03-2017.

**

ORDER:-

Government of Telangana has taken-up restoration of all Minor Irrigation Tanks in the State to their original capacity and to effectively utilize water allocated for Minor Irrigation sector under Godavari & Krishna River Basins as a flagship programme under the name of "MISSION KAKATIYA".

- 2. The Chief Engineer, Minor Irrigation (KB), Hyderabad in his letter first read above has submitted proposal under Mission Kakatiya Phase-III for "Comprehensive Restoration of (28) Minor Irrigation tanks in Siddipet District for according administrative approval.
- 3. Government after careful examination of the matter, hereby accord administrative approval for an amount of Rs.8,68,73,000/- (Rupees Eight Crores Sixty Eight lakhs and Seventy Three Thousand Only) towards "Comprehensive Restoration of (28) Minor Irrigation tanks in Siddipet District for the Financial Year 2017-18 under Mission Kakatiya phase-III Programme, subject to the responsibility of the Chief Engineer, Minor Irrigation (KB), Hyderabad, to follow the following points while giving Technical Sanction and while executing the work. The statement showing the details of tanks sanctioned for restoration is annexed to this order:-
 - He must ensure and satisfy from the history of repairs carried out to the tanks that there are no overlap of proposed repairs in any other previous sanctioned schemes, now on-going are taken up recently.
 - 2) The cost of repairs must be arrived after thorough investigation and as per the actual requirement of components are quantities for restoration and the provisions made including lump sum provisions are in terms of codal provisions and the guidelines issued in relation thereto.

- 3) Whenever applicable, the de-siltation provision made in the estimates are based pre-levels and prudent assessment of quantities involved and in consideration of nature of percolation and potential of the yield.
- 4) Follow due procurement procedures for taking up the works.
- 5) Dismantling of existing damage Structures and construction of new weir and sluice shall be done only in rare cases after due examination of the possibilities of repairs of the existing damage structures at a level not lower than Superintending Engineer.
- 6) Ensure sufficient funds in 2017-18 BE to meet the expenditure towards MK programme works including sanctions considered now before giving technical sanction
- 4. The expenditure sanctioned in para (3) above shall be debited to the Head of Account "4702 COL on M.I. MH-101-Surface Water GH-11 Normal State Plan SH-(23) Mission Kakatiya 530 Major works 531 Other Expenditure".
- 5. The Chief Engineer, Minor Irrigation (KB), Hyderabad, shall take necessary action accordingly to complete the work within the stipulated period and submit the utilization certificate to Government. The (28) estimates received through the letter 1st read above are returned herewith.
- 6. This order issues with the concurrence of Finance (EBS.IX) Department vide their U.O. No.2837/163 /A2/EBS.IX/2017, Dated:21-03-2017.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

VIKAS RAJ PRINCIPAL SECRETARY TO GOVERNMENT

To

The Chief Engineer, Minor Irrigation (KB), Hyderabad (we) (28) original Estimates)

Copy to:-

The District Collector, Siddipet.

The Finance (EBS.IX) Department.

The Accountant General, T.S. Hyderabad.

The Director of Works & Accounts, M.J. Market Road, T.S., Hyderabad.

PS to Hon'ble Minister (Irrgn, Mrkt, and LA)

PS to Principal Secretary to Government, I & CAD Department.

PA to Dy. Secretary to Government (S), I & CAD Department

SF/SCs (C.No.1928/MK/A2//2017).

//forwarded by order //

\mathbf{c}	\sim T	\sim	-		\sim	ᄆ
3E	O I	ION	ı U	ГГ	ıv	ᄄ

ANNEXURE-I
Statement showing the details of tanks sanctioned for Restoration under Mission Kakatiya Phase-III inSiddipet District- List-X

SI. no	Unique Code	Geo-tagging ID	Name of the Tank	Habitation H/O Village	Mandal	Constituency	Ayacut	Amount Sanctioned for Repairs component Rs in Lakhs	Amount Sanctioned for Desiltation Rs in Lakhs	Total Sanctioned for the work Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11
1	030304602501306	790043182103	Ooracheruvu	Regulapally	Bejjanki	Manakondur (SC)	65.0	34.62	16.28	50.90
2	030304601901305	790467182672	Gandla kunta	Dacharam	Bejjanki	Manakondur (SC)	70.0	17.58	8.62	26.20
3	030304601901307	790524182658	Gaddallakunta/ Gaddaralla kunta	Dacharam	Bejjanki	Manakondur (SC)	62.0	17.62	7.78	25.40
4	030304601804317	790400182849	Mallareddy kunta	Laxmipur (V) / Bejjanki	Bejjanki	Manakondur (SC)	65.0	16.26	12.44	28.70
5	030304601901306	790507182741	Narsimhaswamy kunta	Dacharam	Bejjanki	Manakondur (SC)	60.0	14.55	9.45	24.00
6	030304601901304	790493182751	Dubba kunta	Dacharam	Bejjanki	Manakondur (SC)	65.0	14.56	11.09	25.65
7	030304601101315	790450183394	Narellakunta Vadluri /Narallakunta	Vadlur- Begumpet	Bejjanki	Manakondur (SC)	42.0	11.00	13.40	24.40
8	040414601001101	787441180691	Kamalai cheru	Gudikandula	Thoguta	Dubbak	131.1	36.19	3.96	40.15
9	040331600204301	787618182191	Shalavani Kunta/ Shaloni Kunta	Kodandaraopally H/o Narayanraopet	Siddipet	Siddipet	38.6	10.18	1.22	11.40
10	040412200101102	785693179813	Improvements to Ramdas cheruvu	Doultabad	Doultabad	Dubbak	140.31	146.66	3.35	150.00
11	040331700201309	788571182340	Peddammakunta near Vittalapur	Vittalapur	Chinnakodur	Siddipet	31.0	15.21	0.00	15.21

12	040331702401303	787852182405	Narsimulu Kunta	Matindla	Chinnakodur/ Siddipet Rural	Siddipet	35.2	12.96	3.74	16.70
13	040331700101308	788307182400	Restoration of Damaged protion apron of Polavanikunta	Jakkapur	Chinnakodur/ Siddipet Rural	Siddipet	50.0	21.90	0.00	21.90
14	040331800601301	789874180811	Bandam Kunta	Rampur	Nangnoor	Siddipet	35.0	8.27	0.73	9.00
15	040331701501308	788145181971	Feeder Channel Achoni Kunta To Peddarayan Cheru Malyal	Malyal	Chinnakodur/ Siddipet Rural	Siddipet	31.0	18.20	0.00	18.20
16	040331700302316	789452182445	Feeder channel on Surplus course of Gandi cheru to Gundavaram cheruvu	Kishtapur	Chinnakodur	Siddipet	38.5	31.96	0.00	31.96
17	040331701201309	788874181864	Feeder channel Across surplus cours of Erra cheru to Brahamndla kunta	Machapur	Chinnakodur	Siddipet	72.1	41.75	0.00	41.75
18	040331700901302	789796181558	Feeder channel from Mallaram village to Feeder Channel of surpluscource of Mogullakunta	Mallaram	Chinnakodur	Siddipet	45.0	40.50	0.00	40.50
19	040331700601302	789924181731	Feeder channel surplus course of pallecheru to Shanigaram Tank	Cherlankireddy pally	Chinnakodur	Siddipet	60.0	54.95	0.00	54.95
20	030325400801101	790951181639	Feeder channel from Oora cheruvu Nagasamdrala (V) to Badugula Cheruvu	Nagasamdrala, Koheda, Theegala Kunta pally	Koheda	Husnabad	600.0	106.10	0.00	106.10

21	040331600202505	787564182149	Checkdam across Palnati lasmaiah well	Laxmidevipally H/o Narayanraopet	Siddipet	Siddipet	32.9	13.49	0.91	14.40
22	040331600701507	787599181955	Check Dam near Manthuri Yadhagiri Well	Bachaipally H/o Raghavapur	Siddipet	Siddipet	32.3	5.68	1.22	6.90
23	040331701301311	788440182035	Existing checkdam across Left side near	Gangapur	Chinnakodur	Siddipet	34.1	9.00	0.00	9.00
24	040331801601506	791013180687	Checkdam across Lokati Venkatesham Land	Gatlamalyal	Nangnoor	Siddipet	35.0	9.38	0.54	9.92
25	040331801601505	791033180664	Checkdam across Ravindrachary Land	Gatlamalyal	Nangnoor	Siddipet	35.0	5.06	0.54	5.60
26	040331801501501	790663180840	Check dam a/c of Peddavagu near Baswapur Road	Akkenapally	Nangnoor	Siddipet	80.0	43.76	0.54	44.30
27	040331801601501	791105180751	Check dam a/c of Garibotulavagu near Rajesaham fields	Gatlamalyal	Nangnoor	Siddipet	35.0	8.90	0.54	9.44
28	040331801601201	791000180722	Anicut A/c Matuvorrey near Muthaiah fields	Gatlamalyal	Nangnoor	Siddipet	35.0	5.37	0.73	6.10
							2056.09	771.65	97.09	868.73

VIKAS RAJ PRINCIPAL SECRETARY TO GOVERNMENT

//forwarded by order//

SECTION OFFICER